

Model	6k Service	12k Service	24/48k Service	Cam belt change
Porsche 924 - all models	£105	£195	£235	£87
Porsche 944 - all models	£195	£325	£370	£425
Porsche 928 - all models	£245	£378	£435	£450 (16v or 32v)
Porsche 968 - all models	£155	£315	£370	£395
Porsche 1963 - 1988 except Turbo	£210	£485	£567	
Porsche 930 Turbo Models	£210	£695	£790	
Porsche 964 C2, C4, RS, 3.3 & 3.6	£210	£590	£645	
Porsche 964 Turbo Models	£240	£575	£790	
Porsche 993 C2, C4, C2S, C4S & RS	£240	£375	£570	
Porsche 993 GT2 & Turbo	£240	£335	£595	

Model	12K Service	24K/36K Service	48K Service	Belt Change
Porsche 996 C2, C4, & S	£230	£325 2000-01 models £471 2002 on	£390	£95
Porsche 996 GT & Turbo	£245	£660	£731	On application
Porsche 997 C2, C4 & S	£235	£350	£385	£95
Porsche 997 Gen 2	£235	£335	£745 £855 (PDK)	£95
Porsche 997 GT & Turbo	£270	£682	£745	On application
Porsche 991 except GT, Turbo	£275	£545	£685	
Porsche 991 GT & Turbo		Pricing on application		

Model	20K Service	40K Service	60K Service	Belt Change
Porsche Boxster 987 2.7 & S	£245	£315	£425	£95
Porsche Boxster 987 Gen 2 2.7 & S	£245	£320	£675	
Porsche Boxster (981)	£285	£337	£590* £685 (PDK)	*included in major
Porsche Cayman 987C	£245	£315	£425 £595 (PDK)	£95
Porsche Cayman 981C	£285	£337	£590* £685 (PDK)	*included in major

Model	20k Service	40k Service	60k Service	80k Service	120k Service
Porsche Panamera	£240	£360	£455 £545 (PDK)	£440	£545
Porsche Panamera 4/4S/GTS/S	£250	£370	£455 £545 (PDK)	£450	£545
Porsche Panamera Diesel	£370	£470	£420 £630 (PDK)	£470	£500
Porsche Panamera Turbo S	£250	£600	POA	POA	POA

Model	20k Service	40k Service	60k Service	80k Service	160k Service
Porsche Cayenne V6	£205	£390	N/A	£456	£995
Porsche Cayenne S	£235	£320	£546	£395	£852
Porsche Cayenne Turbo	£235	£495	£546	£546	£995
Porsche Cayenne Turbo S & GTS	Please Contact Us for Prices				

Fixed price Gearbox oil and filter change £350.00 plus VAT

**Miscellaneous**

Porsche Boxster  
 Porsche 996  
 Porsche 997  
 Other models

**Evans Coolant**

from £455  
 from £530  
 from £530  
 Please enquire

Porsche Boxster (986)  
 Porsche Boxster (987)  
 Porsche Boxster (987 Gen2)  
 Porsche 911 (996)  
 Porsche 911 (997)  
 Porsche 911 (991.1)  
 Other models

**Clutch Replacement**

From £750  
 From £760  
 From £925  
 From £875  
 From £975  
 From £1025  
 Please enquire

All models

**Brake Fluid Replacement**

£95, discounted with service

All models, all servicing

**Waste oil disposal and Sundries**

£14.99

Porsche Boxster and 911 (996)  
 Porsche Boxster and 911 (996) Tip

**IMS Bearing Replacment**

£1,595.00  
 £1,695.00

*includes oil and filter, flywheel bolts  
 and new rear main seal*